

NIS-elements Hot Key	Function
<b>Acquisition</b>	
+	start scanning
-	stop scanning
CTRL + -	capture
CTRL + "space bar"	auto capture
mouse wheel	enable mouse joystick Z, move Z drive
CTRL + N	optical configurations
CTRL + ALT + M	Ti pad
CTRL + ALT + Y	XYZ Navigation
CTRL + ALT + J	A1 Scab Area
CTRL + ALT + C	A1 Simple GUI
<b>Analysis</b>	
mouse wheel	scroll through Z stack zoom in/out
F12	split image component view
Shit + N	contrast enhancement
CTRL + Shift + N	component contrast
CTRL + ALT + L	LUTs
CTRL + ALT + H	histogram
CTRL + ALT + S	synchronizer
CTRL + ALT + P	preview
Shift + S	smooth
CTRL + ALT + Q	threshold
Shift + F5	object measurement setup
Shift + F6	field and ROI measurement setup
F7	measure length
F5	perform measurement
Shift + F7	intensity profile
CTRL + ALT + T	time measurement
CTRL + ALT + R	ROI statistics
CTRL + Shift + right/left/up/down	shift image
CTRL + Shift + O	calibrate documents
ALT + "enter"	image properties
<b>View</b>	
F10	organizer layout
CTRL + F1	thumbnails